## Oil Field Environmental Incident Summary

**Date/Time of Notice:** 05/20/2015 13:52 Incident: 20150520135252 Responsible Party: XTO ENERGY INC. Well Operator: XTO ENERGY INC. Well Name: LUNDIN 11-15SEH Field Name: SIVERSTON Well File #: 20097 Date Incident: 5/20/2015 Time Incident: 07:30 Facility ID Number: **MCKENZIE** Twp: 150 **Rna**: 98 **Sec:** 15 **Qtr:** County: Location Description: Submitted By: Shawn Dahl Received By: Shawn Dahl Contact Person: P.O Box 6501 Englewood, CO 80155 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Stuffing Box Leak Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled Units Recovered Units Followup **Units** 2 Barrels 2 Oil Barrels **Brine** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: None Areal Extent:

## Potential Environmental Impacts:

None

## Action Taken or Planned:

Stuffing box rubbers changed.

Wastes Disposal Location: Free standing liquid was put back in the production tanks, impacted soil

will be removed and taken to an approved disposal facility.

Agencies Involved:

## **Updates**

Date: 5/20/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.